



Tesoro Logistics GP, LLC
1801 California Street, Suite 1200
Denver, CO 80202

August 29, 2017

US EPA Region 8
Air and Radiation Program, 8P-AR
1595 Wynkoop Street
Denver, CO 80202-1129

**Re: 40 CFR Part 60, Subpart OOOO/OOOOa Semi-Annual Report
Ironhorse Complex Gas Plant - Ironhorse II Process Train
Uintah County, Utah**

Dear Sir or Madam:

Tesoro Logistics-Rockies (TLR), operator of the Ironhorse Complex Gas Plant, is pleased to submit this 40 CFR 60, Subpart OOOO/OOOOa (Quad O/Oa) semi-annual report on behalf of QEP Field Services, LLC.

As required by 40 CFR §60.636, §60.5420 and §60.5420a TLR is providing this semiannual monitoring report for Ironhorse II process train. This report covers the time period of February 1, 2017 through July 31, 2017.

During the reporting period, there were 39 components which were not previously identified or monitored as required by 40 CFR 60.482-7a(a)(1)&(a)(1)(i). 38 of the 39 components identified are connectors that require annual monitoring. The components were located under soft pack insulation. These components have been tagged and added to the monitoring program.

During the reporting period, one connector was placed on delay of repair because it required a joint pipeline and process unit shutdown. The component was subsequently repaired in April. Additionally, the facility had a process unit shutdown for seven days between 7/10/2017-7/17/2017. All components on delay of repair were repaired and re-monitored during that time.

If you have any questions concerning this report, please contact me by phone at (303) 454-6676 or by email at Heather.L.Vainisi@tsocorp.com.

Sincerely,

A handwritten signature in black ink, appearing to read "Heather Vainisi", written over a horizontal line.

Heather Vainisi
Senior Environmental Specialist – LDAR Coordinator